




Pells Sullivan Meynink Pty Ltd



NOTE: MONITORING BY HDC

Newmont Waihi Gold Ltd
Risk Assessment Pumphouse Re-Location

SEDDON STREET CRACKS - (ZONE 1)
VERTICAL MOVEMENTS

PSM 125.L88

Figure 4