




Pells Sullivan Meynink Pty Ltd

Newmont Waihi Gold Ltd
Risk Assessment Pumphouse Re-Location

SEDDON STREET CRACKS - (ZONE 1)
HORIZONTAL MOVEMENTS

PSM 125.L88

Figure 3



NOTE: MONITORING BY HDC