




Pells Sullivan Meynink Pty Ltd

Newmont Waihi Gold Ltd  
Risk Assessment Pumphouse Re-Location

SEDDON STREET CRACKS - (ZONE 1)  
VERTICAL MOVEMENTS

PSM 125.L88

Figure 4



NOTE: MONITORING BY HDC