Historic Heritage Inventory



Black Rock Milking Shed, Waihi



Location: SH25 (Oldfield Road) Corbett Road corner - about 6km from Waihi along the LHS.

Heritage Status

Historic Places Trust Registration Number:

Historic Places Trust Category:

HDC Heritage Category: A - Heritage Feature. National or Outstanding

Regional Significance

Other:

Physical Description: Quarried rock face formed into an underground milking shed.

Other known names:

Notable features:

Style:

Materials: Natural Rock

Date of Construction: c.1920s

History: In 1910 a miner, Andy Scobie, bought land for a farm and after breaking in enough land to sustain a small herd, he undertook a unique and ambitious scheme to cut a cowshed out of the rock using his mining skills. This he did with the help of his father, George, who was also a miner. Andy also

District Plan Schedule

Number: HAU276
Heritage Category: A

Heritage Type:

- Wahi Tapu
- Cultural Landscape
- Building
- ☐ Group of Buildings
- Structure
- Monument
- Historic Place
- □ Archaeological Site
- Other

Date Period: 1910-1940

Significance:

- Archaeological
- Architectural
- Cultural
- □ Historic
- Scientific
- Technological

Thematic Context

- Maori
- Early Settlement
- Industry
- Extraction
- Forestry
- Agriculture
- Transport
- Communication
- Commerce
- Residential
- Social/Cultural
- ☐ Civic
- □ Health
- Educational
- ☐ Church/yard
- Other

Historic Heritage Inventory



Black Rock Milking Shed, Waihi

considered building a house in the rock above the shed but the cheap price of conventional houses (around £50 to £100) caused him to abandon that idea.

In 1929 the Scobie family sold the farm to Peter Brady whose son, Charlie, took over the farm in 1935. He built a conventional cowshed nearer to the road. In 1945 the farm was sold to Jim Kennedy, and he was the last owner known to have used the shed. It became a storage room for hay. Later owners were the Stolp family, the De Vries family, Fred Thomas, George Mara, Mr Fagan and now Alan and Ruth Scott. The shed has now filled with sediment because the cow track runs beside it and a person can no longer stand up inside.

Architect:
Designer:
Builder:
Engineer:

History of changes:

Condition: good

Integrity: substantially intact

Current Uses: private farmland (Scott Farm)

Former Uses:

Registered owner:

Legal Description:

Reference Source: Waihi Historical Society

Associated Pictures:



District Plan Schedule Number: HAU276

Heritage Category: A